

TWIST MONITORING TOOL. APPLIED TO A RATCHET WRENCH IT CAN BE USED AS A TORQUE WRENCH. BACKLIT LCD SCREEN, PEAK AND TRACE...



Operation mode

MEASURE UNITS:

Capacity

Reading

Memory

Accuracy

Dimensions

Battery

Working temperature

Storage temperature

Gross weight

EAN Code

Peak/track

Nm/kgm/kgcm/lbft/lbin

40 - 200 Nm

0,1 Nm g

50

±2%

75 x 44mm

1 x 3 V CR2032

-10°C-60 °C (14°F-139.9 °F)

-20°C -70°C (-4 °F-157.9°F)

0,41 kg

8012667382544



Box



Cr-V

-



Plastic

-



1/2"



1/2"



Chromed